



9990

Fire Door Top Gap Solution — *Up To 90 Minutes*

PRODUCT CUT SHEET

PROJECT:
SUBMITTED BY:
DATE:
NOTES:

UL Certified for Door Top Gaps — Measuring up to 1/2".




- 90-Minute Rated — for Use on UL10B and UL10C Wood or Hollow Metal Fire Doors
- No Need to Move Hardware at the Top of the Door
- Works on Doors with Parallel Arm Closers
- Patent Pending
- Available in 36" and 48" Lengths
- Brushed Stainless Steel
- End Caps Furnished Standard
- Non-Handed

PRODUCT CONSISTS OF:

- + #304 Brushed Stainless Steel Flat Plate - Pull Side
- + #304 Brushed Stainless Steel Intumescent Cap — Push Side
- + #304 Brushed Stainless Steel End Caps
- + #6 X 3/4" Stainless Steel SMS Furnished

FINISH:

Brushed Stainless Steel



NGP-FDA-GAP-PCS-0221-A

NGP MEMPHIS
4985 East Raines Road
Memphis, TN 38118
orders@ngp.com

NGP VEGAS
4584 Calimesa Street
Las Vegas, NV 89115
vegasorders@ngp.com

ngp.com
1-800-NGP-RUSH